LA-50T-1V

Before assembly Please spend some times to read this and follow the procedures step by step. Some panels are viewed differently from the exploded drawing below. This is for extra clarity.
Do not discard any of the packaging until you have checked all the parts and the package of fittings. If you are missing any of the parts, please contact the store from which you purchased your products. The staff will do their best to help you.

Check list

❶ x4 ❷ x4 ❸ x1

❹ x1 ❺ x1 ❻ x1

❼ x2 ❽ x1 (4mm)

❾ x1

❿ x1

⓫ x1



Step 1

Place LCD with facing downward on flat surface. Place VESA on the LCD back as figure and align to the screwholes. Secure them together with four screws .And then tighten them up with screwdriver(not provided).





2008.11.13

Assembly Guide

Step 2

Loosen two screws slightly. Put the arm into the post and adjust it to the suitable position.



Tighten it up with 4mm Allen key. finally, put in the plug.

Step 3



Step 4

Use cable cover supplied to finish cable management. Secure them together with four screws.And then Nylon nut is loose,please use the Wrench to tighten the arm.





2008.11.13